

风太大了

来说说不走运的事。最近的一场暴风雨摧毁了 SatcoDX 在印尼卫星自动搜索基站的 1.8 米天线。底座无法抵抗暴风雨强大的风载。当然，重新竖起天线要花费一些金钱。我们都要从这次事故中汲取教训错误！



■ 此前：1.8 米的天线矗立在 SatcoDX 印尼扫描基站的屋顶上，它有 6 瓣，用来接收 $113^{\circ} E$ 的 PALAPA C2 和 $125.5^{\circ} E$ 的 CHINASAT 6B 卫星(用天线的偏焦接收)。实际上，它并不位于首都雅加达，而是在马来西部群岛西部的坤甸。如果需要，极轴电机会将其一直向东转到 $166^{\circ} E$ 接收 INTELSAT 8 卫星，或向西对准 $49^{\circ} E$ 的 YAMAL 202 卫星。你还能看到空调旁边另外有两个小天线，它们也属于自动搜索基站。

Download this report in other languages from the Internet:

- | | | |
|------------|------------|--|
| Arabic | العربية | www.TELE-satellite.com/TELE-satellite-0909/ara/indonesia.pdf |
| Indonesian | Indonesia | www.TELE-satellite.com/TELE-satellite-0909/bid/indonesia.pdf |
| Bulgarian | Български | www.TELE-satellite.com/TELE-satellite-0909/bul/indonesia.pdf |
| Czech | Česky | www.TELE-satellite.com/TELE-satellite-0909/ces/indonesia.pdf |
| German | Deutsch | www.TELE-satellite.com/TELE-satellite-0909/deu/indonesia.pdf |
| English | English | www.TELE-satellite.com/TELE-satellite-0909/eng/indonesia.pdf |
| Spanish | Español | www.TELE-satellite.com/TELE-satellite-0909/esp/indonesia.pdf |
| Farsi | فارسی | www.TELE-satellite.com/TELE-satellite-0909/far/indonesia.pdf |
| French | Français | www.TELE-satellite.com/TELE-satellite-0909/fra/indonesia.pdf |
| Greek | Ελληνικά | www.TELE-satellite.com/TELE-satellite-0909/hel/indonesia.pdf |
| Croatian | Hrvatski | www.TELE-satellite.com/TELE-satellite-0909/hrv/indonesia.pdf |
| Italian | Italiano | www.TELE-satellite.com/TELE-satellite-0909/ita/indonesia.pdf |
| Hungarian | Magyar | www.TELE-satellite.com/TELE-satellite-0909/mag/indonesia.pdf |
| Mandarin | 中文 | www.TELE-satellite.com/TELE-satellite-0909/man/indonesia.pdf |
| Dutch | Nederlands | www.TELE-satellite.com/TELE-satellite-0909/ned/indonesia.pdf |
| Polish | Polski | www.TELE-satellite.com/TELE-satellite-0909/pol/indonesia.pdf |
| Portuguese | Português | www.TELE-satellite.com/TELE-satellite-0909/por/indonesia.pdf |
| Romanian | Românesc | www.TELE-satellite.com/TELE-satellite-0909/rom/indonesia.pdf |
| Russian | Русский | www.TELE-satellite.com/TELE-satellite-0909/rus/indonesia.pdf |
| Swedish | Svenska | www.TELE-satellite.com/TELE-satellite-0909/sve/indonesia.pdf |
| Turkish | Türkçe | www.TELE-satellite.com/TELE-satellite-0909/tur/indonesia.pdf |

Available online starting from 31 July 2009



■ 之后: 多么令人惋惜, 1.8 米的天线被大风吹倒了。



■ 几瓣天线、还有支座, 以及 LNB 都损坏了。